



**Department of Transport
Air Accident Investigation Unit
25 Clare Street
Dublin 2**

**☎ 01-604 1293
01-2411777**

Fax:- 01-604 1514

**E-mail Address:- aaiu@transport.ie
www.aaiu.ie**

FINAL REPORT

SERIOUS INCIDENT

to

**MD 11
N803DE**

at

Dublin Airport

3 February 2002

*Notification of Accidents or Incidents should be made on the
24 hour reporting line
01-604 1293*

CONTENTS	Page
NOTIFICATION	1
SYNOPSIS	2
FACTUAL INFORMATION	2
1.1 History of the flight	2
Witness Observations	5
1.2 Injuries to persons	8
1.3 Damage to aircraft	8
1.4 Other damage	9
1.5 Personnel Information	11
1.5.1 Commander (Captain)	11
1.5.2 Co-pilot (First Officer)	11
1.5.3 Relief (First Officer)	11
1.6 Aircraft Information	12
1.6.1 General Description	12
1.6.2 Leading particulars	12
1.6.3 Technical examination	13
1.6.4 Aircraft Procedures/Guidance/Limitations	14
1.7 Meteorological Information	20
1.7.1 General	20
1.7.2 Terminal Area Forecast (TAF)	20
1.7.3 Meteorological Reports (METAR's)	20
1.7.4 Weather pattern in the days leading up to the 3 February 2002	20
1.7.5 Rainfall amounts in the period leading up to runway excursion	21
1.7.6 Weather conditions prevailing over hours leading up to the runway excursion	21
1.7.7 Wind conditions from 07.00 hours to 08.30 hours on the 3 February 2002	21
1.7.8 Synopsis of wind and weather conditions prevailing about the time of touchdown	22
1.7.9 Wind regime at the time of landing	23
1.7.10 ATIS and Pilot Reports	23
1.7.11 Wind measuring equipment at Dublin Airport	24

1.8	Aids to Navigation	25
1.9	Communications	25
1.10	Aerodrome Information	26
1.10.1	General	26
1.10.2	Physical characteristics of runways	26
1.10.3	Surface friction/Test/Runway Condition	27
1.10.4	Tyre marks on runway/graded surface	28
1.10.5	Airport/runway closure	29
1.10.6	Aircraft recovery	29
1.10.7	Airport grassland	29
1.11	Flight Recorders	30
1.11.1	Cockpit Voice Recorder (CVR)	30
1.11.2	Digital Flight Data Recorder (DFDR)	31
1.12	Wreckage and Impact Information	33
1.13	Medical and Pathological Information	33
1.14	Fire	33
1.15	Survival Aspects	33
1.15.1	General	33
1.15.2	Events immediately after the aircraft came to a halt	33
1.15.3	Preparation for disembarkation	37
1.15.4	Disembarkation	39
1.15.5	Reception at the Terminal Building	41
1.15.6	Emergency Planning /Exercises	41
1.16	Test and Research	41
1.17	Organizational and Management Information	42
1.17.1	The Airport Authority	42
1.17.2	The Operator	43
1.17.3	The Handling Agent	44

1.18	Additional Information	44
1.18.1	The International Civil Aviation Organisation (ICAO)	44
1.18.2	Maximum Demonstrated Crosswind	45
2	Analysis	46
	Meteorological Information	46
	Runway Surface Condition	48
	The Runway Excursion	48
	The Emergency Response	59
	Aircraft Recovery	59
	Discussion	59
3	Conclusions	61
3 (a)	Findings	61
3 (b)	Cause	63
4	Safety Recommendations	64
5	Appendices	66
	Appendix A - Relevant sequence of events and ATC Transmissions	66
	Appendix B - Airport layout/site location	69
	Appendix C - Flight Operations Manual – Hydroplaning	71
	Appendix D - Dublin Weather Radar picture for 08.00 and 08.15 hours	77
	Appendix E - Anemometer continuous wind trace readings	81
	Appendix F - Defining Average Wind and Gust	83
	Appendix G - Defining the Runway Surface Condition	89
	Appendix H - Trace of DFDR plots	91
	Appendix I - Airport Authority Emergency Response Directive No 3	93
	Appendix J- Extracts from ICAO Annex 3 and Annex 14	95

